

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

**REMARKS**


In this Preliminary Amendment, the specification has been amended to correct cross-references to related applications, consistent with the priority benefits claimed under 35 U.S.C. §119(e), and 35 U.S.C. §120 in the above-identified application. No new matter is added. Pursuant to MPEP §201.11 and 37 C.F.R. §1.78(a)(2) and (a)(5), these benefit claims are proper as being made during the pendency of the present application and within four months from the actual filing date of the present application.

Additionally, the specification and drawings have been amended to address various typographical errors and inconsistencies in reference numerals noted during the preparation of formal drawings for this application. Again, no new matter is added.

Favorable action is requested.

Respectfully submitted,

*George Mueller, et al.*

By:   
Joseph Teja, Jr., Reg. No. 45,157  
LOWRIE, LANDO & ANASTASI, LLP  
One Main Street  
Cambridge, Massachusetts 02142  
United States of America  
Telephone: 617-395-7000  
Facsimile: 617-395-7070

Attorney Docket No.: C1104-7127.30  
Date: July 7, 2004

2/71




Fig. 2




Fig. 3

4/71






Fig. 4



7/71



8/71





Fig. 8

10/71

Fig 10B



1002

SEG  
10B

Fig 10 A

10

$\frac{11}{71}$




Fig. 11

13/71

1304

500

1302




Fig. 13




Fig. 16




Fig. 17

18/71

1802





Fig 18/71

Fig 18/73

Fig. 18

19/71




Fig. 19

23/71




Fig. 23

27/71




Fig. 27

28/71




Fig. 28

31/71




Fig. 31




Fig. 32

40/71




Fig. 40

41/21





Fig. 41

42/71



LED board - direct view

Fig. 42B

43/71






Fig. 43

44171



45171



१३३४ नवं दिल्ली अमेरि

46/71




Fig. 46 A B C D

48/71




Fig. 48A

Fig. 48B

Fig. 48

54/71




Fig. 54 A 513 )




Fig. 56

5702





Fig. 57



5804

5802

Fig. 58




Fig. 59




Fig. 60

67/71




FIG. 67A

FIG. 67B




FIG. 67C

Fig. 67




Fig. 70